

Trenchless CIPP Liners, Gone Wrong.

Are you sure you are getting long-term water recovery if you are not correctly inspecting the quality of repairs?


CIPP Defects Not Found, Recorded, or Measured By CCTV



1. Post-CIPP, Bad Invert Connection



2. Post-CIPP, Bad Service Reconnection



3. Wrinkles




4. Accelerant Burns, Called Out As Discolored, But Leaks



5. Bad Resin. Installed less than 16 months prior.



6. Defective/Weak Liner



7. Overcooked Liner



8. Unreported Contractor Damage



9. Defective Epoxy



10. Misreported Bad Reconnection. Same Leak Running 4 Years.



11. Annular Space




12. Bad Sectional Spot Repair



13. Infiltration Spotting



14. Bulges



15. Missed Lateral Reinstatement



16. Bad Epoxy Lining



17. Sag In Liner




CIPP Liner Installed in 2017 by national CIPP contractor.

18. Defective Top-Hats



CIPP Liner Installed in 2014 by national CIPP contractor.

19. Pinhole Leaks



20. Infestation



21. Post-CIPP Misaligned / Open Joint



22. Blistering