
electro scaning.

Evolution of a Sewer Sinkhole









An aging sewer... a
A 50-year old sewer has been
televised multiple times in the past
20 years, with no visible defects.

allows soil to leak through bad joints creating a void... so the pavement gives way...

Defective joints, not seen by CCTV inspection, periodically surcharge and systematically liquifies soil above the sewer pipe, creating a void. City crews have a PM to remove silt, without knowing that a void is being created.

Without a base under it, the pavement collapses, opening a hole wide enough and deep enough to swallow a car.

An unsuspinto the sir continues continues

An unsuspecting car plunges into the sinkhole as the hole continues to widen.

